



Public Summary - RSB audit

MBP Solutions Ltd

Certificate Number: CUC/RSB/820040/304693

Cret Taconnet 13, 2000 Neuchatel, Switzerland

CERTIFIED	EXPIRATION
2-8-2018	1-8-2023

DATE(S) OF AUDIT
17-4-2020, 18-5-2020, 8-9-2020
and 9-2-2021
date of last update
01-04-2021

Control Union Certifications, Meeuwenlaan 4-6, 8011 BZ, Zwolle, The Netherlands 0031 (0) 38 426 0100 certification@controlunion.com certification.controlunion.com

FOREWORD

Methodology

Control Union Certifications (CUC), is an international inspection and certification Audit and certification is carried out in conformity with the procedures as laid down Based on the information provided by the auditor and by the client, the certifier reviews and evaluates all information provided and certifies the products when all conditions of the regulations are fulfilled. The result of the evaluation is documented in this report and the applicable Annexes. Audit work by the auditor and certification by the certifier are clearly separated activities.

Report

This report is the result of the findings of a certification evaluation carried out by an independent lead auditor or team of experts representing Control Union Certifications. The purpose of the assessment was to evaluate the compliance of the client with respect to the standards used within the scope of the certificate. The report is made in accordance with standard RSB-PRO-70-001. The full report can only be reviewed by authorized Control Union and RSB staff.

In case of any complaint or appeal with respect to findings and certification decisions taken by CUC, a dispute protocol and form is available on the CUC website:

http://certifications.controlunion.com/publications and can also be provided on request.

CONTENTS

ME	3P Solu	ıtions Ltd	1
Ce	rtificat	e Number: CUC/RSB/820040/304693	1
FO	REWO	RD	2
со	NTEN	TS	3
SE	CTION	A – PUBLIC SUMMARY	4
1.0)	GENERAL INFORMATION	4
	1.1	Operator Information	4
	1.1.1	Name and Contact Information	4
	1.1.2	Additional Parties Involved	4
	1.2	Scope of Certificate	4
	1.3	Standards Used	5
	1.3.1	Applicable RSB-Accredited Standards	5
	2.1	Audit Type and Determination	6
	2.2	Audit Team	6
	2.3	Evaluation Schedule and Extent of Audit	6
	2.3.1	Determination of Extent of Audit	6
	2.3.2	Activities Duration and justification audit	7
	2.4	Stakeholder Consultation Process	7
3.0	RISK	ASSESSMENT RESULTS	8
4.0)	RESULTS OF THE EVALUATION	8
	4.1	Process of Determining Compliance	8
	4.1.1	Non-Compliance	8
	4.1.2	Evaluation of Non-conformities	8
	4.1.3	Identified non-conformities during present evaluation	8
	4.1.4	Assessment of non-compliance raised during and after previous audit report	8
	4.1.5	Major Non-compliances	9
	4.1.6	Non-compliances and Current Status	9
5.0	CERT	FICATION DECISION1	6

SECTION A – PUBLIC SUMMARY

1.0 GENERAL INFORMATION

1.1 Operator Information

1.1.1 Name and Contact Information

Organization name	MBP Solutions			
Contact person	Davide Vallero			
Operator Number	1409 CUC PRJ number PRJ 820040			
Address	Cret Taconnet 13	Telephone	+41 793 03 4167	
	2000 Neuchatel Switzerland	Fax	N/A	
		e-mail	dva@mbpgroup.eu	
	Website	www.mbpsolutions.com		

112	Δdditional	Dartics	Involved
11/	Anniiionai	Pariles	invoiven

Is not included (Confidential)		

1.2 Scope of Certificate

Please select audit:		☐ RSB Global
Please select boxes that apply:	☐ Pre-assessment	☐ 1st Annual Surveillance
	☐ Initial Assessment	
	☐ Re-certification	☐ 3rd Annual Surveillance
	☐ Follow-Up to NCs	☐ 4th Annual Surveillance

CERTIFICATION SCOPE				
Trader and first collector of waste/residue-based biofuels and bio liquids, mechanical operator.				
Please select boxes that apply:	☐ Biomass producer			
	☐ Point of Origin			
	☑ First collector			
	☐ Industrial operator			
	☑ Mechanical operator			
	⊠ Trader			
The scope assessment agrees with the scope under which the operator applied	☑ Yes □ No			
If no, please explain:	In addition to storage of the material, processing (dewatering) ha also taken place. The scope of first collector and trader did not co			

	this. The scope has been extended during the audit process.
Note: If the scope is different, please contact CU.	

Participating site head office		
Name	MBP Solutions Ltd	
Address Cret Taconnet 13, 2000 Neuchatel, Switzerland		
Participating site storage		
Name	MBP Bio Production AS	
Address	Greakerveien 127, 1718 Greaker, Norway	

Description of activities		
	Collecting, storing, processing purchasing and trading of waste and residues (Fatty Acids, Crude Glycerin, Glycerol, FOEE, Ester residues, Fish residues and soap stock).	
Annual throughput of previous 12 months is not included (Confidential)		

1.3 Standards Used

1.3.1 Applicable RSB-Accredited Standards

Title	Version
RSB Standard for EU Market Access (RSB-STD-11-001)	V3.2
RSB Procedure for Participating Operators (RSB-PRO-30-001)	V3.2
RSB EU RED Standard for Traceability (Chain of Custody) (RSB-STD-11-001-20-001)	V3.6
RSB Procedure on Communications and Claims (RSB-PRO-50-001)	V3.5
RSB EU RED Standard for the certification of biofuels based on waste and residues (RSB-STD-11-001-010)	V1.2
RSB Procedure for Risk Management (RSB-PRO-60-001)	V3.2
RSB EU RED GHG Calculation Methodology (RSB-STD-01-003-01)	V2.3

All standards employed are available on the websites of the Roundtable on Sustainable Biomaterials (RSB Procedures & Standards Archives | RSB).

2.0 EVALUATION PLANNING & PROCESS

2.1 Audit Type and Determination

The following table summarizes the audit types for RSB Audits:

	Low risk class	Medium risk class	High risk class
Certificate validity	5 years	3 years	2 year
Main audit	Every 5 years	Every 3 years	Every 2 year
Surveillance audit	Annual	Annual	Annual

2.2 Audit Team

Names auditteam:	Chris Pen	Auditor role:	Lead auditor
Names auditteam:	Loek Verwijst	Auditor role:	GHG expert

2.3 Evaluation Schedule and Extent of Audit

2.3.1 Determination of Extent of Audit

Total number of subsidiaries, branch offices, affiliated entities, external third parties contracted or otherwise engaged, operational structures, sites, facilities, processing and production units, and supply chain structures	1 head office (remote audited) 4 PoO's (2 visited, 1 on-site and 1 remote due to covid restricions) 1 storage site (ISCC certified EU-ISCC-Cert-DE105-82736607) remotely audited
Participating Operator Risk Class	Low risk
Disputes or prior Non-compliances	N/A
Changes in scope since last evaluation	Yes, also mechanical operator.
Total number of compliance claims	14

2.3.2 Activities Duration and justification audit

Duration and justification audit		
Audit Duration (in hours):	2 nd annual surveillance audit:	
	Additional verification:	
	Preparation time: 2 hours	
	Remote office audit: 8 hours	
	Remote storage audit: 3 hours	
	Onsite and remote audits POOs: 6 hours	
	Reporting: 10 hours	
	Total: 29 hours	

Description of the annual surveillance audit / evaluation		
Operation(s)/ sites visited Activities/ notes		
17-4-2020 Participation site I	Opening Meeting: scope of audit confirmation	
	Evaluation of documented/company system	
	Closing meeting	
18-5-2020 storage MBP Bio Production AS (Greaker)	Opening meeting, General requirements, Traceability, Procedure for Communication and claims, Closing meeting	
8-9-2020 Mercuria Biofuels GmbH & Co (point of origin)	Opening meeting, General requirements, Traceability, Procedure for Communication and claims, Closing meeting	
9-2-2021 Adesso Bioproduct AB (point of origin)	Opening meeting, General requirements, Traceability, Procedure for Communication and claims, Closing meeting	

People interviewed annual surveillance audit

Participating site I MBP Solutions Ltd: Davide Vallero, Yingxiao Leng, Milva Mihaylova

Storage MBP Bio Production AS (Greaker): Kari Anne Lund, Heidi Nielsen, Davide Vallero, Yingxiao Leng

POO Mercuria Biofuels GmbH & Co: Tarkan Savasogan POO Adesso Bioproduct AB: Phillipp Graber, Runar Jensen

Action taken by the organization prior to (re)issue of certificate

The self-risk assessment has been carried out and provided. MBP System Description for EU RED Compliance- RSB Manual and RSB mass balances 2019/2020 were provided.

2.4 Stakeholder Consultation Process

Not applicable, the scope of MBP Solutions Ltd has the scope trader, first collector and mechanical operator

3.0 RISK ASSESSMENT RESULTS

CUC Risk Assessment Results	3	Low risk
Participation Operator Assessment Results	3	Low risk
Deviations and Risk Factor Difference	No both 3 and low risk	
Final risk class, based on the findings of the audit (structural NC's), the risk has increased form Low in Medium		Low Medium High

Due to the results of the Risk Assessment, the evaluation did not need to be rescheduled.

4.0 RESULTS OF THE EVALUATION

4.1 Process of Determining Compliance

4.1.1 Non-Compliance

Non-compliance: failure to comply with one or more requirements specified in the RSB standards and/or the RSB certification systems

4.1.2 Evaluation of Non-conformities

CUC shall monitor and evaluate all actions taken by the participating operator to address non-compliances finalization of the evaluation report CUC shall evaluate at minimum those aspects of the operation(s) of CUC shall ensure that recommendations to close major non-compliances, and whether major non-compliances were corrected, rectified or otherwise brought into compliance with the RSB standards and the RSB certification systems, together with the respective certification reports are submitted to peer review and duly decided by its certification decision entity.

4.1.3 Identified non-conformities during present evaluation

Non-compliance (NCs) identified during this evaluation are listed below. In case the organization has Each element (requirement) of the Standard is evaluated by means of a checklist. Please refer to the annexed checklists for details.

4.1.4 Assessment of non-compliance raised during and after previous audit report

Check if section is not applicable, i.e. it concerns a main assessment/initial audit, or no NCs were raised Below an overview is given of the actions taken by the client/certificate holder to correct any NC's. For each NC a description of its current status is given. In the case a minor NC has not been settled within 3 months the RSB certificate will be withdrawing

4.1.5 Major Non-compliances

	No major NCs were issued to the Operator during the evaluation. Any minor CARs from previous surveillance audits have been reviewed and closed prior to the issuance of a certificate.
×	Major NCs were issued to the Operator during the evaluation, which have all been closed to the satisfaction of the audit team and meet the requirements of the standards. Any minor NCs from previous surveillance audits have been reviewed and closed prior to the issuance of a certificate.
	Major NCs were issued to the Operator during the evaluation and the Operator has not yet satisfactorily closed all major NCs.

4.1.6 Non-compliances and Current Status

Instructions:

- Initial certification audit: list all Non-conformities and Opportunities for Improvement issued during this audit.
- Surveillance/Recertification: list status of minor NCs that were not closed in previous audit, then list new NCs/OFIs issued during this audit.

Summary of Non-compliances and Current Status		
Non- compliance Number	1	
Category	major	
Relevant RSB Standard & Indicator No	1.4	
Description of requirement	A clear definition of the certification scope is available in written	
Description of non- conformity	Scope and storage sites are not actual in the available manual MBP System Description for EU RED Compliance-RSB Manual dated 05/06/2017.	
Description of actions taken to address non-compliances, the evaluation of those actions and decision to accept them for compliance with RSB standards	Document ID: 21787-X draft, - warehouse (storing) is included in the scope and the feedstocks are missing (Fatty Acids, Crude Glycerin, Glycerol, FOEE, Ester residues, Fish residues and soap stock) - Operational sites has been corrected and agreed	
Status	Closed	

Summary of Non-compliances and Current Status	
Non- compliance Number	2
Category	minor
Relevant RSB Standard & Indicator No	1.11
Description of requirement	The PO carried out a self-evaluation against the RSB standards and procedures

Description of non- conformity	Only results are included in the self-evaluation (internal audit), not the findings against the RSB standards and procedures.
Description of actions taken to address non-compliances, the evaluation of those actions and decision to accept them for compliance with RSB standards	Document self assesment MBP aug 2020: performed August 4th 2020 including the RSB standards & requirements, findings & corrective actions.
Status	Closed

Summary of Non-compliances and Current Status		
Non- compliance Number	3	
Category	major	
Relevant RSB Standard & Indicator No	2.1.2	
Description of requirement	Employees are appropriately trained and have the necessary competence, knowledge and experience to RSB compliant systems in place, especially those working on the chain of custody system and the risk management system	
Description of non- conformity	Training of the new sustainability team member, Milva Mihaylova, has not been documented. The internal training of last year's sustainability team is not effective. See the NCs of this audit.	
Description of actions taken to address non-compliances, the evaluation of those actions and decision to accept them for compliance with RSB standards	Milva Mihaylova and also the other members of the sustainability team participated the online Basic RSB training online 20-8-2020. The effect of the updated porcedures and of learning platform will be assessed during the next annual audit	
Status	Closed	

Summary of Non-compliances and Current Status		
Non- compliance Number	4	
Category	minor	
Relevant RSB Standard & Indicator No	3.1	
Description of requirement	The operator implemented, maintains and updates regularly a risk management system with the elements risk identification, risk assessment, risk mitigation and risk monitoring in line with the RSB EU RED Standard for Risk Management	
Description of non- conformity	Monitoring of the risk management system was not available	
Description of actions taken to address non-compliances, the evaluation of those	Document ID: 21787-4 MBP System Description for EU RED Compliance- RSB Manual dated 5/6/2017 and Changelog Risk evaluation: seen modified procedure and current risk	

actions and decision to accept them for compliance with RSB standards	evaluation.
Status	Closed

Summary of Non-compliances and Current Status	
Non- compliance Number	5
Category	major
Relevant RSB Standard & Indicator No	5.4
Description of requirement	Contractual agreements are available for all purchases and sales of certified material
Description of non- conformity	The wording of the purchased and sold sustainable materials in the contracts of the checked sample were not in accordance with the RSB-STD-11-001-01-010-ver-1.2_RSB-EU-RED-Standard-on-waste-and-residues.
Description of actions taken to address non-compliances, the evaluation of those actions and decision to accept them for compliance with RSB standards	Updated wordings in ERP system. The latest version of the RSB calculation tool (2.13) has been used to calulate the GHG emisions for transport.
Status	Closed

Summary of Non-compliances and Current Status	
Non- compliance Number	6
Category	major
Relevant RSB Standard & Indicator No	6.2
Description of requirement	The following site records are available
Description of non- conformity	The delivery documentation for Croda's direct sales was not available
Description of actions taken to address non-compliances, the evaluation of those actions and decision to accept them for compliance with RSB standards	Seen eamail and preventive action in the manual "monthly check of the mass balance by QM"
Status	Closed

Summary of Non-compliances and Current Status	
Non- compliance Number	7
Category	major

Relevant RSB	
Standard & Indicator No	6.4
Description of requirement	Sufficient details to identify the material are included in every batch of certified material that are acquired, handled or forwarded
Description of non-conformity	- 200-166159 Waste and Residue: Crude Glycerine: RSB cert number not right 304693 instead of 481664 - 200-168187 Waste and Residue: Crude Glycerine: RSB cert number not right 304693 instead of 481664, purchase Glycerine sold Glycerol - 200-168909 Waste and Residues: Soapstock: RSB cert number not right 304693 instead of 481664, Sales contract by product mentioned instead of W/R, GHG Etd 29 Frederikstad - Vra is not correct - 200-169204 Waste and Residues: Ester Residues: RSB cert number not right 304693 instead of 481664, Sales contract and invoice Prichem 1999 Ester instead of Ester residues - 200-169438: Waste and Residue: Crude Glycerine RSB cert number not right 304693 instead of 481664, contract Glycerine instead of Crude Glycerine - 200-169772 Waste and Residue: Food waste: RSB cert number not right 304693 instead of 481664, Contract mentioned PB lauric distillate, wtfn waste downgrade vegetable oil from processing plant, sales contract mixed vegetable acid Selected sample deliveries mass balance: - 200-164830, 200-164828 and 200-164833 Waste and Residues: Fatty Acids: GHG Etd 101 instead of 104, mixed fatty acids instead of Fish residue - 200-163907, 200-163908 and 200-165787 Waste and Residues: Fatty Acids: contract dated 7-8-2018, bio oil mix instead of Fish residue, GHG worst case 18,83 (report 2/7/2004 not updated)
Description of actions taken to address non-compliances, the evaluation of those actions and decision to accept them for compliance with RSB standards	Delivery documents have been corrected and corrections have been made in the used system.
Status	Closed

Summary of Non-compliances and Current Status	
Non- compliance Number	8
Category	major
Relevant RSB Standard & Indicator No	8.3.1
Description of requirement	Each operational site maintains its own mass balance

	accounting system
Description of non- conformity	The wording of transferred sustainable materials from the ISCC mass balance Waste and Residues: Fatty Acids were not in accordance with the RSB-STD-11-001-01-010-ver-1.2_RSB-EU-RED-Standard-on-waste-and-residues.
Description of actions taken to address non-compliances, the evaluation of those actions and decision to accept them for compliance with RSB standards	2020 - RSB Mass Balance: wording is ok
Status	Closed

Summary of Non-compliances and Current Status	
Non- compliance Number	9
Category	major
Relevant RSB Standard & Indicator No	9.0.1 / 9.2.4 / 9.2.9
Description of requirement	The operator uses either default values or disaggregated values or calculates the GHG emissions / savings in accordance with the methodology detailed in RSB-STD-11-001 (actual values), or a combination of disaggregated and actual values
Description of non- conformity	GHG for transport were not calculated correctly, see 6.4. Report with calculated emissions of 2014 is used. No actual check was available.
Description of actions taken to address non-compliances, the evaluation of those actions and decision to accept them for compliance with RSB standards	The latest version of the RSB calculation tool (2.13) has been used to calulate the GHG emisions for transport.
Status	Closed

Summary of Non-compliances and Current Status	
Non- compliance Number	10
Category	major
Relevant RSB Standard & Indicator No	13.1
Description of requirement	Verify that the material is eligible under the RSB standard for waste and residues
Description of non- conformity	The wording of the purchased and sold sustainable waste and residues of the checked sample were not in accordance with the RSB-STD-11-001-01-010-ver-1.2_RSB-EU-RED-Standard-on-waste-and-residues.

Description of actions taken to address non-compliances, the evaluation of those actions and decision to accept them for compliance with RSB standards	Screenshot of the used system shows the wording waste and residues: Biomass fraction of industrial waste, Crude glycerine, processing residues, spent bleaching earh, Tall oil pitch, UCO vegetable and animal. Inplementation will be reviewed during the onsite follow up.
Status	Closed

Summary of Non-compliances and Current Status	
Non- compliance Number	11
Category	major
Relevant RSB Standard & Indicator No	1.9
Description of requirement	Contracts with all elements of the certification scope are in place, including their commitment - to comply with RSB Standards and procedures, and - to provide unrestricted access to any elements of the certification scope
Description of non- conformity	Available contract MBP Solutions Ltd - MBP Bio Production AS dated 27-1-2020, comply with the RSB standards and rented storage capacity is not included.
Description of actions taken to address non-compliances, the evaluation of those actions and decision to accept them for compliance with RSB standards	Updated contact available dated 13-8-2020
Status	Closed

Summary of Non-compliances and Current Status	
Non- compliance Number	12
Category	major
Relevant RSB Standard & Indicator No	2.1.2
Description of requirement	Employees are appropriately trained and have the necessary competence, knowledge and experience to RSB compliant systems in place, especially those working on the chain of custody system and the risk management system
Description of non- conformity	No training system or training records are available from the relevant employees involved with the MBP Bio Production AS RSB system.
Description of actions taken to address non-compliances, the evaluation of those actions and decision to accept them for compliance with RSB standards	The members of the sustainability team participated the online Basic RSB training online 20-8-2020. The effect of the updated porcedures and of learning platform will be assessed during the next annual audit

Status	Closed
--------	--------

Summary of Non-compliances and Current Status			
Non- compliance Number	13		
Category	major		
Relevant RSB Standard & Indicator No	1.4		
Description of requirement	A clear definition of the certification scope is available in written		
Description of non- conformity	In addition to storage of the material, processing (dewatering) of e.g. ref numbers 200-165800 and 200-166457 has also taken place. Both quantities of the products "Biogas mix" and "Biooil mix" have been transferred from the ISCC mass balance to the RSB mass balance. The scope of warehouse does not cover this.		
Description of actions taken to address non-compliances, the evaluation of those actions and decision to accept them for compliance with RSB standards	Document ID: 21787-X draft, mechanical operator has been included in the scope		
Status	Closed		

Summary of Non-compliances and Current Status			
Non- compliance Number	14		
Category	major		
Relevant RSB Standard & Indicator No	8.3.6, 8.3.9 and 8.3.13		
Description of requirement	The operator regularly (e.g. monthly) reconciles the RSB EU RED and/or EU RED certified inputs and outputs. The operator ensures that positive balance is only reported into the next reporting period if the corresponding amount of material is physically in stock.		
Description of non- conformity	The closing stock of 31-12-2019 (1134 mt) did not match with the quantity shown on the inventory of the tanks present (645 mt). MBs are not aligned to the stock reports		
Description of actions taken to address non-compliances, the evaluation of those actions and decision to accept them for compliance with RSB standards	Seen eamail and preventive action in the manual "monthly check of the mass balance by QM"		
Status	Closed		

5.0 CERTIFICATION DECISION

Certification Recommendation					
Operator to compliance	Yes ⊠ No □				
The CUC evaluation team makes the above recommendation for certification based on the full and proper execution of the CUC Responsible Biofuels Program evaluation protocols. If certification is recommended, the Operator has satisfactorily demonstrated the following without exception:					
Operator ha	Yes ⊠ No □				
Operator has demonstrated that their system of management is capable of ensuring that all of the requirements of the applicable standards are met over the sites and facilities covered by the scope of the evaluation.					
Operator has demonstrated that the described system of management is being implemented consistently over the sites and facilities covered by the scope of the certificate.					
Comments and/or details of any issue which was difficult and/or impossible to evaluate: due to travel restrictions the audit is not yet finalized. This is an intermediary report.					
	Technical Review by: If different to decision-maker	Glenn Feryn (RSB CU certifier)		
To be completed by Certification Decision-Making Entity	Certification decision:	The Organization has been (re-)assessed by CUC according to the standard(s) described in Section 3.			
	Certification decision by:	Glenn Feryn			
	Date of decision: For initial or continued certification	01-04-2021			
	Surveillance schedule:	Surveillance audit 2021 will take place in May (still need to be confirmed)			